<b>Work Orde</b> <i>July-11-12 10:4</i>		234		*872	34	<b>k</b> .							Page 1	
Item ID: Revision ID:	D350-578-0	31		Accept	*N	900	<b>040</b>	100	)* s	etup	Start	*N:	S1*	
Item Name:	Wearplate										Stop	*N:	S2*	
Start Date:	7/24/12	Start Qty: 1.00	*1*		Cu	st Item I	D:							
Required Date:	7/30/12	Req'd Qty: 1.00	*1*		Cu	stomer:								
Reference:														
Approvals:	Process Pl	an:	Date: 12071	Tooling:		Da	ıte:		R	lun	Start	*N	R1*	
	QC:	<b>/</b>	Date:	SPC (Y/N):		Da	ıte:				Stop	*N	R2*	
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	1	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp	
Draw Nbr	Re	vision Nbr												
DSI9429	Re	vA												
IIN D350-578	Re	vA				-0 <b>A</b> 3								_
*100		DOCUMENT CONTRO	)L	0.00		16	17/04	112	4	A	lar	MUJ	12-0	<u>1</u> —1
DC		Memo		0.00			( ) (	,		$\mathcal{F}$				•
Document Control		Photocopy b 001	oluefile and type labels per	PPP D350-578-031 and	DS19429	CHG (								
105		Pick Kit		0.00							//	1		`\
*105* Packaging		Memo		0.00							<u> [[c]</u>	1/2/1	7 (1)	)
Packaging												6		

# **Dart Aerospace Ltd**

	-								
W/O:	N/O:		WC	RK ORDER CHANG	ES				•
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					·	v 1			
			•						
Part No	•	PAR #:	Fault Cate	jory:	_ NCR: Yes	No <b>DQ</b>	A:	Date:	
•	Res	olution:	Disposition	): <u>`</u>	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCF	1)			
DATE	STEP	Description of NC	<u> </u>		ion B	Verific	cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
·									
		·							
									ŧ

130

OC21- Final Inspection - Work Order Release

0.00

QC

Memo

Quality Control

0.00

12/9/19 70 MF 1209-18

Dart Aerospace I	Lta
------------------	-----

W/O:			W	ORK ORDER CHANG	ES			٥ ,
DATE	STEP	PRO	CEDURE CHA	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								÷
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQA:	Date: _	
	Re	esolution:	Disposition	on: <u>`</u>	_ QA: N/C CI	osed:	Date: _	
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCR	)		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	on B Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
			Onioi Eng	Office Eng	Dute			
								,

. Picklist Print

July-11-12 10:43:04 AM

Work Order ID:

87234

Parent Item:

D350-578-031

Parent Item Name:

Wearplate

**Start Date: 7/24/12** 

Required Date: 7/30/12

Page 1

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
ANGEGRA		Purchased	No			105	Each	349.0000	12	12	//		
> Bolt		•		•		1 04-	-	C- 1-					8
				<b>Location</b>		Loc Qty	L	oc Code					
				ST358		300							
					5704	0			12.1	611			
					541	300			/ <del>d</del> /	541			
				ST359		49							
					011	0 44							
					.068	5						_	
D38594041		Name Cantagan d	No	121	.000	105	Each	2.0000	2	,			
Wearplate		Manufactured	140			103	Lucii	2.0000	8			/10	- 86
wearpiate				T		1 06-		C					01
1				Location		Loc Qty		oc Code					
				ST500		2			70	100			
				796	587	2				687			1
MS21042L4		Purchased	No			105	Each	1,124.0000	12	12	1224	C2 /	
/ Nut									<del></del>		1209	320	
				<b>Location</b>		Loc Qty	. <u>L</u>	oc Code					
				ST300		1124							
				. 119	9075	116							
				. 12	1011	193					* .		
				. 12	1444	686					4		

129

121652

## **Dart Aerospace Ltd**

	•									
W/O:			WC	RK ORDER CHANG	ES			··		<i>O</i> ~ <sub>p</sub> ⊲e
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					•					
					-					
Part No	•	PAR #:	Fault Cate	jory:	_ NCR	: Yes N	lo <b>DQ</b> /	A:	_ Date: _	
	Re	solution:	Disposition	n: <u>`</u>	QA:	N/C Clo	sed:		Date:	
NCR:		,	WORK ORDI	ER NON-CONFORM	ANCE	(NCR)	)			
DATE	STEP	Description of NC			tion B	0: 0	Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
									ţ	
					·					
		· · · · · · · · · · · · · · · · · · ·								
										ŧ
					1					

## **Picklist Print**

July-11-12 10:43:05 AM

Work Order ID:

87234

Parent Item:

Washer

D350-578-031

Parent Item Name:

Wearplate

Purchased

No

ST351

107321

**Start Date: 7/24/12** 

Required Date: 7/30/12

Page 2

Start Qty: 1.00

Required Qty: 1.00

Loc Code Loc Qty Location ST298 88 3 104746 116805 119097 27 47 121255 121708 11 ST299 1749 1749 121912

1,840.0000

105

Each

3 3

# **Dart Aerospace Ltd**

W/O:			WORK ORDER CHANGES							
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	y.									
Part No		PAR #:	Fault Cat	tegory:	NCF	R: Yes N	lo <b>DQ</b> /	A:	Date:	
		esolution:								
NCR:			WORK ORI	DER NON-CONFOR	MANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action S Action Description	Section B	Sign &	Verific		Approval	Approval
		Section A	Chief Eng	Chief Eng	,,, 	Date	Section	on C	Chief Eng	QC Inspector
						٠.				
										,

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D350-578 REV. F OR EARLIER
AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D350-578 REV. 1 OR EARLIER REF. TCCA STC: SH93-4

REF. TCCA STC. SH93-4 REF. FAA STC: SR00028NY REF. FAA STC: SR00029NY REF. EASA STC: EASA.IM.R.S.01389 EFERENCE ONLY REF. ARGENTINA STC: CTS-0508.13(A) EFERENCE ONLY

The D350-578-031 Wearplate kit can be installed on D350-578-011/-021 Bearpaw installations. The D3859-041 Wearplates should be installed on the D2432F or D2672F Bearpaws as shown in Figure 1 on Sheet 2 of this Service Instruction. The Bearpaws should otherwise be installed on the skidtube per installation instructions D350-578 Rev F or earlier.

Customers with old style bearpaws will need to rework the counterbore on the bottom of the bearpaws per Figure 1 on Sheet 2 of this service instruction.

### WEIGHT AND BALANCE

		Lateral			Longitudinal			
Installation	Weight	Arm	Moment	Arm Mom				
D350-578-031 Wearplate Kit	3.00 lb 1.36 kg	0.0 in 0.0 m	0.0 in-lb 0.0 m-kg	157.0 in 3.99 m	471.0 in-lb 5.43 m-kg			

#### **PARTS LIST**

QTY. -031	PART NUMBER	DESCRIPTION
Х	D350-578-031	Wearplate Kit
12	کےD3859-041_	Wearplate
12	AN4-17A 🖊	Bolt
12	NAS1149D04630	Washer
7 12	MS21042L4	Nut or (MS21042-4)

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION **BRANCH** DAO # 01-O-01

DATÉ: CERT. NO.: 09.01.15 SH93-4 ISSUE NO.:

Α	NEW IS	SUE		1	09.01.15			
REV.			DESCRIPTION	BY	DATE			
DESIG			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA					
CHECKED		13	DRAWING NO.	77 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	REV. A			
MFG. A	APPR.	N/A	DSI 9429		SHEET 1 OF 2			
APPRO	OVED	149	TITLE		SCALE			
DE APPR.		-#-	WEARPLATE KIT		NTS			
DATE	09.0	1.15	THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS S NOT TO BE USED FOR ANY PURPOSE OR COPIED OR CO	COPYRIGHT @ 2009 BY DART AEROSPACE LTD  IT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS SED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT MORTERS PERSONS FOR MINERAL REPORTS AFE LTD.				